



## SPEED MULTIPLIER


F.MOL

INPUT/OUTPUT RATIO 1:2

It will be fitted between the motor and the pulley case. Maximum spindle speeds must be:

F.P7	15.000	giri/min.	Max
F.10	10.000	giri/min.	Max
F.14	10.000	giri/min.	Max
F.20	10.000	giri/min.	Max

F.MOL (F.7) code 10450010  
F.MOL (F.10) code 10450020  
F.MOL (F.14-F.20) code 10450030



Metric sizes